

POSTED at
29/06/2025, 09:10



STEWARDS' DECISION

From: The Stewards

To: Paul Motorsport

The Stewards, having received a report from the Race Director and reviewed Timekeeping evidences, have considered the following matter and determine the following:

No. / Driver: 333 - Marzio Moretti

Competitor: Paul Motorsport

Time: 08:44

Session: Race

Fact: Exceeded the speed limit in the pit lane with a speed of 50.2km/h

Offence: Breach of Article 27.4 and 28.11 of the GT World Challenge Europe powered by AWS 2025 Sporting Regulations, Article 12.2.1.j of the FIA International Sporting Code and Chapter IV Article 5c) of Appendix L to the Code

Decision: Time penalty 5 seconds to be served at next pit stop

Reason: Timekeeping data shows that car 333 crossed the "PITOUT" timing loop in the pit lane at a speed of 50.2kph, thereby exceeding the 50 kph pit lane speed limit. The Stewards determine that this is a breach of Article 34.11 of the above regulations and impose the penalty specified in accordance with that Article.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code, within the applicable time limits.

Yves BACQUELAINE
Chair Steward

Luís Roby
Steward

Edith VIEIRA DA SILVA
Steward

Francesco MAFFEZZONI
Steward

Jordi PARRO
Steward

Michael SCHWÄGERL
Steward

RECEIPT TO BE CONFIRMED ELECTRONICALLY BY THE COMPETITOR

Luis Roby
Chair-Steward
PT25-0485
29/06/2025, 09:08:04

Francesco Maffezzoni
Steward
ACI 229201
29/06/2025, 09:08:05

Michael Schwaegerl
Steward
DMSB SPA1058504
29/06/2025, 09:08:05

powered by  TotalEnergies



6860e654826879040ac6142d