

The Stewards, having received a report from the Race Director, having examined timekeeping evidence, summoned and heard from the competitor's representative, have considered the following matter and determine the following:

No. / Driver:	14 / Mick Wishofer
Competitor:	Emil Frey Racing
Time (fact):	09:07 hrs
Session:	Qualifying 1
Fact:	Car 14 exceeded the 50 kph pit lane speed limit with a speed of 50.1 kph
Offence:	Breach of Article 34.11 of the Fanatec GT Challenge Europe powered by AWS Sporting Regulations
Decision:	Fine of €50
Reason:	Timekeeping data shows that car 14 crossed the "PITOUT" timing loop in the pit lane at a speed of 50.1 kph, thereby exceeding the 50 kph pit lane speed limit. Having summoned and heard from the driver and the competitor's representative, the Stewards determine that this is a breach of Article 34.11 of the above regulations and impose the penalty specified in accordance with that Article.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code, within the applicable time limits.

Greg MASTERS Steward (Chairman)

FANATEC

Horburg

Richard NORBURY International Steward

Xavier NAVÈS

ASN Steward

SRO New Structure

iĝi

The competitor is reminded that fines must be paid to:

SRO MOTORSPORT FUND EURO BANK ACCOUNT SWIFT CODE RBOSGB2L IBAN GB05 RBOS 1610 7010 1487 81

RECEIPT TO BE CONFIRMED ELECTRONICALLY BY THE COMPETITOR



THANK YOU FOR CONSIDERING THE ENVIRONMENT BEFORE PRINTING THIS DOCUMENT

aws meeti 130 Repairon Audi Sport CIR In mobileye